

Problem: Flex in plastic backing plate

- Some wheel/tire combinations can cause a plastic backing plate to flex during balancing affecting accuracy
- Poor repeatability
- Come-backs

Solution: Improved Light Truck Front Cone Kit

Front Cone Kit 28mm I.D. **No. 8113276**

Front Cone Kit 40mm I.D. **No. 8113277**

- **Solid metal backing plate eliminates flex** - 7.91" O.D.
- Double Sided Cone - Range: 4.80"-6.80"
- Available in 28mm & 40mm I.D.
- Components available separately
 - Front Double Sided Cone 28mm I.D. **No. 8113279**
 - Front Double Sided Cone 40mm I.D. **No. 8113280**
 - Backing Plate 28mm I.D. **No. 8113060**
 - Backing Plate 40mm I.D. **No. 8113061**

HENNESSY INDUSTRIES, INC.

Manufacturer of Ammco[®], Coats[®] and BADA[®] Automobile Service Equipment, Tools and Accessories

1601 J.P. Hennessy Drive LaVergne, TN 37086-3565 800-688-6496 or 615-641-7533

Hennessy Canada: 2430 Lucknow Drive, Unite 9, Mississauga, Ontario L5S 1V3 905-672-9440

www.ammcoats.com