



Tire Service Solutions

Problem: X Model Rim Clamp Tire Changers cannot externally clamp 6" ATV wheels or 22" wheels

22" wheels are in the marketplace

ATV wheel service is a fast growing market segment

A large installed base of X-model rim-clamp tire changers exists that are not equipped to handle these assemblies.

Upgrading to new equipment is not always a feasible solution.

Solution: Extended X-Clamps



Part No. 8184926

Externally clamp the new larger diameter wheels **up to and including 22"** without damage. Externally clamp ATV wheels **down to 6"** in diameter without the cost of special ATV adapters.

Fit all COATS "X" Model Rim Clamp Tire Changers.

COATS Part #8183604 "Quilted Clamp Socks" fit these clamps to avoid marring expensive alloy wheels.

Kit includes 4 replacement spring loaded clamp position buttons.

About the same cost as a conventional set of ATV adapters plus you get 22" external clamping capability.

Can easily be installed by user.

HENNESSY INDUSTRIES, INC.

Manufacturer of Ammco®, Coats® and BADA® Automobile Service Equipment, Tools and Accessories
1601 J.P. Hennessy Drive LaVergne, TN 37086-3565 800-688-6496 or 615-641-7533

Hennessy Canada: 2430 Lucknow Drive, Unite 9, Mississauga, Ontario L5S 1V3 905-672-9440

www.ammcoats.com

Rev 3/02